Oil Field Environmental Incident Summary

Responsible Party: EOG Resources, Inc.
Well Operator: EOG RESOURCES, INC.
Well Name: ROUND PRAIRIE 9-3625H

Field Name: PAINTED WOODS Well File #: 18538

Date Incident: 12/3/2012 Time Incident: 10:00 Facility ID Number:

County: WILLIAMS Twp: 154 Rng: 103 Sec: 36 Qtr: SE SE

Location Description:

Submitted By: Luigi Heydt Received By:

Contact Person: Luigi Heydt

P.O. Box 639

Stanley, ND 58784

General Land Use: Well/Facility Site

Affected Medium: Well/Facility Soil

Distance Nearest Occupied Building:

Distance Nearest Water Well:

Type of Incident: Other

Release Contained in Dike: Yes - On Facility Site Reported to NRC: No

	Spilled	Units	Recovered	Units
Oil	2	barrels	0	barrels
Brine	0	barrels	0	barrels
Other	0	barrels	0	barrels

Description of Other Released Contaminant:

Inspected: Written Report Received: Clean Up Concluded:

Risk Evaluation:

Areal Extent:

Followup Units

Potential Environmental Impacts:

Action Taken or Planned:

A loader was is being used to removed the affected soil on the well pad surface. The soil will then be hauled off to disposal.

Wastes Disposal Location: Indian Hills Disposal.

Agencies Involved:

Updates

Date: 12/3/2012 Status: Reviewed - Assigned to Other Agency Author: Roberts, Kris

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Release remained on location according to the report.